



Approved CR

IAA Chicago South
16425 S Crawford Ave
Branch No 515
Markham, IL 60426
(708) 333-5700/(708) 333-5756
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 NISSAN KICKS**
Sport Utility
Bodystyle/Series: **Vehicle S XTRONIC CVT**
Color: **Black**
Mileage: **50,395 (Verified)**
Turn-in Mileage: -
VIN: **3N1CP5BVXLL518741**
Work Order/
Stock Number: **46380311**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: **G413361W**
Vehicle Grade : **Grade 3.4**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order: -



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 205 / 60 R 16

Car Tire Size - LR 205 / 60 R 16

Car Tire Size - RR 205 / 60 R 16

Car Tire Size - RF 205 / 60 R 16

LF Tires - 7/32 inch

LR Tires - 7/32 inch

RF Tires - 7/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - STARFIRE

Tire Brand - Front Right - STARFIRE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE


Tire Model - RR - FT140

Tire Model - RF - Solarus As

Tire Model - LR - FT140

Tire Model - LF - Solarus As

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	R Bumper Textured	Multiple Scratches Heavy	-	3

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper Cover Upper	Cracked	-	2 To 3 Inches
	Hood	Chipped	-	5
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	> 12 Inches
	Roof	Chipped	-	3
	Right Rear Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Front Bumper Tow Hook Cover	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.