Approved CR

America`s Auto Auction - Richmond
3600 Deepwater Terminal Road
Richmond, VA 23234
804-232-7355/804-232-1818
richmond.fleet@americasaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD TAURUS**
Bodystyle/Series:	**4 Door Vehicle SEL 4D SEDAN AWD**
Color:	**WHITE**
Mileage:	**61,815 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FAHP2H83KG108732**
Work Order/ Stock Number:	**000843934**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G11-0280W**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• PRIOR POLICE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**All Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

4th Passenger Door	ABS Brakes	Air Conditioning
All Wheel Drive	Automatic Headlights	Auxiliary Pwr Outlet
Bluetooth Connection	Brake Assist System	CD Player
Car Tire Size - RF tire size P235/55HR18	Car Tire Size - RR tire size P235/55HR18	Car Tire Size - LR tire size P235/55HR18
Car Tire Size - LF tire size P235/55HR18	Child Safety Locks	Cruise Control
Cylinders - 6	Driver Air Bag	Dual Air Conditioning
Empty Weight - 4140 lb	Engine Immobilizer	Floor Mats
Heated Mirrors	Independent Climate Control	Intermittent Wipers
Keyless Entry	Keyless Start	LF Tires - 8/32 inch
LR Tires - 11/32 inch	Leather Steering Wheel	MP3 Radio
Master Key - 2key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Driver & Passenger Seat
Power Driver Seat	Power Lock	Power Mirrors
Power Steering	Power Trunk/Liftgate	Power Windows
Privacy Glass	RF Tires - 7/32 inch	RR Tires - 12/32 inch
Rear Defrost	Rear Parking Aid	Remote Trunk Release
Reverse Camera	Seat Trim - Cloth	Security System
Side Airbags - Front	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Generic	Tire Brand - Front Right - RF tire mfg Generic
Tire Brand - Rear Left - LR tire mfg Generic	Tire Brand - Rear Right - RR tire mfg Generic	Tire Pressure Monitor System
Traction Control	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Left Front Fender	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Left Rear Door	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Right Front Door	Multiple Dents/No Paint Damage	Repair	6
	Right Rear Door	Multiple Dents/Paint Damage	Repair	7

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.