



Approved CR

IAA Eugene
1000 Bethel Drive
Branch No 309
Eugene, OR 97402
(541) 689-4000/(541) 689-0083
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-250**
Bodystyle/Series: **Extended Cab
XL**
Color: **Gray**
Mileage: **89,114
(Verified)**
Turn-in Mileage: **-**
VIN: **1FD7X2B64KEC36143**
Work Order/
Stock Number: **46379669**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632679V**
Vehicle Grade : **Grade 1.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment



Additional Equipment:

Car Tire Size - LF 265 / 70 R 17	Car Tire Size - LR 265 / 70 R 17	Car Tire Size - RR 265 / 70 R 17
Car Tire Size - RF 265 / 70 R 17	LF Tires - 9/32 inch	LR Tires - 6/32 inch
RF Tires - 9/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - MAZAMA
Tire Brand - Front Right - MAZAMA	Tire Brand - Rear Left - MAZAMA	Tire Brand - Rear Right - MAZAMA
Tire Model - RR - Open Range A/T Plus	Tire Model - RF - Open Range A/T Plus	Tire Model - LR - Open Range A/T Plus
Tire Model - LF - Open Range A/T Plus		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Right Rear Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	-	6
	Left Bed Side	Chipped	-	2
	Left Rear Wheel	Corrosion	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	1 To 2 Inches
	Roof	Chipped	-	4
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Cab Side	Heavy Scratch	-	3 To 4 Inches
	Exterior Rear Body Panel	Multiple Scratches Heavy	-	3
	Front Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.