



Approved CR

IAA Baton Rouge
5978 Hwy 75
Branch No 422
Carville, LA 70721
(225) 686-9197/(225) 686-8197
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
1500**
-
Bodystyle/Series: **TRADESMAN
4X2 6'4 BOX**
Color: **Blue**
Mileage: **68,296
(Verified)**
Turn-in Mileage: -
VIN: **1C6RR6FGXJS303613**
Work Order/
Stock Number: **46390455**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G420861V**
Vehicle Grade : **Grade 3.2**
Remarks: -
Announcements:

- Active Codes
see IAA
Condition
Report

Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	No
Engine Size:	3.6 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /-	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 70 R 17

Car Tire Size - RF 235 / 70 R 17

Car Tire Size - LF 235 / 70 R 17

Car Tire Size - LR 235 / 70 R 17

LF Tires - 11/32 inch

LR Tires - 11/32 inch

RF Tires - 12/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - SAILUN

Tire Brand - Front Right - SAILUN

Tire Brand - Rear Left - SAILUN

Tire Brand - Rear Right - SAILUN

Tire Model - RR - Terramax HLT

Tire Model - RF - Terramax HLT

Tire Model - LR - Terramax HLT

Tire Model - LF - Terramax HLT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	8
	Hood	Chipped	-	2
	Right Front Fender	Multiple Scratches Heavy	-	4
	Right Bed Side	Multiple Scratches Heavy	-	4
	Right Rear Wheel	Corrosion	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Fender	Chipped	-	3
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Right Front Door	Scraped	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Multiple Scratches Light	-	3
	Tailgate	Multiple Dents/Paint Damage	-	2
	Left Front Door	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.