



Approved
CR

IAA Colorado Springs
8500 Import Ct
Branch No 377
Colorado Springs, CO 80925
(719) 755-0862/(719) 715-0988
mgr-coloradosprings@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-350**

Bodystyle/Series: **Crew Cab XL**

Color: **White**

Mileage: **76,628 (Verified)**

Turn-in Mileage: **-**

VIN: **1FT8W3B6XKEE97228**

Work Order/
Stock Number: **46363753**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631201W**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements:

**• HOLE IN ROOF
FROM
AFTERMARKET
ANTENNA**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

LF Tires - 8/32 inch

LR Tires - 11/32 inch

RF Tires - 14/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - RR - Wrangler Duratrak RT

Tire Model - RF - Wrangler Duratrak RT

Tire Model - LR - Wrangler Duratrak RT

Tire Model - LF - Wrangler Duratrak RT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Running Board	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Right Front Wheel	Corrosion	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Chipped	-	4
	Tailgate	Chipped	-	3
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Roof	Chipped	-	3
	Cab - Left	Multiple Dents/Paint Damage	-	3
	Left Rear Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Mirror Cover	Broken	-	Replacement Required
	Right Front Mirror Signal Lamp	Broken	-	Replacement Required
	Right Drip Rail Molding	Misaligned	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.