



Approved CR

IAA Fresno
1805 N Lafayette Ave
Branch No 337
Fresno, CA 93705
(559) 264-5033 / (559) 264-4251
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
FUSION**
Bodystyle/Series: **4 Door Sedan
S**
Color: **White**
Mileage: **45,993
(Verified)**
Turn-in Mileage: **-**
VIN: **3FA6P0G77LR201543**
Work Order/
Stock Number: **46248610**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G101357X**
Vehicle Grade : **Grade 3.0**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 60 R 16	Car Tire Size - RF 215 / 60 R 16	Car Tire Size - LF 215 / 60 R 16
Car Tire Size - LR 215 / 60 R 16	LF Tires - 3/32 inch	LR Tires - 4/32 inch
RF Tires - 4/32 inch	RR Tires - 3/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Assurance	Tire Model - LR - Assurance	Tire Model - RF - Assurance
Tire Model - RR - Assurance		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Bug Damage	-	Repair Required
	Right Front Fender	Chipped	-	3
	Right Rear Tire	Worn	-	Replacement Required
	Deck Lid	Chipped	-	2
	Left Qtr Panel	Chipped	-	2
	Overall Vehicle	De-Identify	-	Removal Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Front Tire	Worn	-	Replacement Required
	Left Drip Rail	Chipped	-	3
	Lf Mirror Cover	Chipped	-	3
	Rf Mirror Cover	Chipped	-	3
	Right Drip Rail	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.