



Approved CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
COLORADO**

Bodystyle/Series: **Extended Cab
WT**

Color: **White**

Mileage: **23,632
(Verified)**

Turn-in Mileage: **-**

VIN: **1GCHSBEA6G1308756**

Work Order/
Stock Number: **46409036**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G43B5166**

Vehicle Grade : **Grade 3.8**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Power - Driver Only	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 16	Car Tire Size - RF 265 / 70 R 16	Car Tire Size - LF 265 / 70 R 16
Car Tire Size - LR 265 / 70 R 16	LF Tires - 12/32 inch	LR Tires - 9/32 inch
RF Tires - 12/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - SUMITOMO
Tire Brand - Front Right - SUMITOMO	Tire Brand - Rear Left - SUMITOMO	Tire Brand - Rear Right - SUMITOMO
Tire Model - LF - Encounter HT2	Tire Model - LR - Encounter HT2	Tire Model - RF - Encounter HT2
Tire Model - RR - Encounter HT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Cracked	-	2 To 3 Inches
	Right Front Fender	Multiple Dents/Paint Damage	-	2
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.