Approved CR

IAA Tidewater
211 Production Drive
Branch No 725
Yorktown, VA 23693
(757) 595-8493/(757) 595-8691
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 CHEVROLET SILVERADO 2500HD**
Bodystyle/Series:	**Crew Cab WT**
Color:	**Black**
Mileage:	**108,226 (Verified)**
Turn-in Mileage:	-
VIN:	**1GC1KREG5KF213860**
Work Order/ Stock Number:	**46404714**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G630992V**
Vehicle Grade :	**Grade 2.2**
Remarks:	-
Announcements:	• repairs may be needed and Rust • Warning indicator on
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Synthetic Leather /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: **Power Brakes**

Additional Equipment:

Car Tire Size - RR 33 / 12.50 R 20	Car Tire Size - RF 33 / 12.50 R 20	Car Tire Size - LF 33 / 12.50 R 20
Car Tire Size - LR 33 / 12.50 R 20	LF Tires - 7/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LF - Wrangler Duratrac	Tire Model - LR - Wrangler Duratrac	Tire Model - RF - Wrangler Duratrac
Tire Model - RR - Wrangler Duratrac		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Aftermarket	-	Acceptable
	Right Front Wheel	Aftermarket	-	Acceptable
	Warning - Tire Pressure	On	-	Unacceptable
	Warning Light - Engine	On	-	Unacceptable
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Left Rear Wheel	Aftermarket	-	Acceptable
	Left Front Wheel	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Multiple Scratches Heavy	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Rust	-	Severe Damage
	Front Bumper Extension	Aftermarket	-	Replacement Required
	Inside Bed	Multiple Dents/Paint Damage	-	3
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches
	Left Rear Wheel	Curb Rash	-	> 12 Inches
	Left Running Board	Rust	-	Severe Damage

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	9 To 10 Inches
	Left Front Wheel	Curb Rash	-	> 12 Inches
	Right Drip Rail	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.