



Approved CR

Capital City Auto Auction
600 Winfield Rd
St. Albans, WV 25177
(304) 201-2270/(304)201-2284
brandon@capitalcityaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2026 TOYOTA CAMRY**
Bodystyle/Series: **4 Door Vehicle LE 4D SEDAN FWD**
Color: **WHITE**
Mileage: **39 (Verified, 6 digits)**
Turn-in Mileage: **-**
VIN: **4T1DAACK4TU905772**
Work Order/ Stock Number: **001432767**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G10D6308**
Vehicle Grade : **Grade 0.0**
Remarks: **-**
Announcements: **-**
Certification : **Not Certified**
Req. Prev. Repair Order: **-**



Drivable: No

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

4th Passenger Door	ABS Brakes	Adaptive Cruise Control
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet
Blind Spot Monitor	Bluetooth Connection	Brake Assist System
Car Tire Size - LF tire size P205/65VR16	Car Tire Size - LR tire size P205/65VR16	Car Tire Size - RF tire size P205/65VR16
Car Tire Size - RR tire size P205/65VR16	Child Safety Locks	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Dual Air Conditioning	Empty Weight - 3450 lb	Engine Immobilizer
Front Wheel Drive	Front Wheel Drive	Heated Mirrors
Independent Climate Control	Intermittent Wipers	Keyless Entry
Keyless Start	LED Headlights	LF Tires - 0/32 inch
LR Tires - 9/32 inch	Lane Departure System	Master Key - 2key(s)
Motor Fuel Type - Other	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Trunk/Liftgate	Power Windows
Privacy Glass	RF Tires - 8/32 inch	RR Tires - 9/32 inch
Rear Defrost	Remote Trunk Release	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Firestone	Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone
Tire Brand - Rear Right - RR tire mfg Firestone	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Turn Signal Mirrors
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Broken	Replace	Replacement Required
	Hood	Broken	Replace	Replacement Required
	Left Head Lamp	Broken	Replace	Replacement Required
	Left Qtr Panel	Severe Damage	Replace	Replacement Required
	Left A Pillar	Multiple Scratches Heavy	Repair	10 Or More
	Left Front Door	Severe Damage	Replace	Replacement Required
	Left Front Fender	Severe Damage	Replace	Replacement Required
	Left Mirror	Severe Damage	Replace	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Broken	Replace	Replacement Required
	Left Rear Door	Severe Damage	Replace	Replacement Required
	Left Tail Light	Broken	Replace	Replacement Required
	Right Rear Bumper/Cover	Torn	Replace	> 12 Inches
[no photo]	Left Front Tire	Worn	Replace	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.