Approved CR

Greater Rockford Auto Auction
5937 Sandy Hollow Road
Rockford, IL 61109
(815) 874-7800/(815) 874-7009
BSchneider@graa.net
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2017 FORD POLICE INTERCEPTOR UTILITY** |
| Bodystyle/Series: | **4 Door Sport Utility Vehicle AWD 4D SUV 4WD - POLICE** |
| Color: | **WHITE** |
| Mileage: | **59,608 (Verified, 6 digits)** |
| Turn-in Mileage: | - |
| VIN: | **1FM5K8AR2HGB41579** |
| Work Order/ Stock Number: | **000666852** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G625686S** |
| Vehicle Grade : | **Grade 3.1** |
| AutoGrade : | **3.1 - Average** |
| Remarks: | - |
| Announcements: | • FORMER POLICE UNIT<br>• MISSING REAR DOOR PANELS |
| Certification : | **Not Certified** |
| Req. Prev. Repair Order: | - |

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **Yes** |
| Engine: | **6-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **3.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |

## Equipment

| | | | |
|---|---|---|---|
| Radio: | **AM/FM CD** | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /BK** | Rear Defroster: | **Yes** |
| Airbag: | **Dual Air Bags** | Tilt Steering: | **Yes** |
| Seats: | **Power** | Drive Type: | **All Wheel Drive** |
| Seat Count: | - | Brakes: | **Power Brakes** |

Additional Equipment:

| | | |
|---|---|---|
| ABS Brakes | Adjustable Pedals | Air Conditioning |
| All Wheel Drive | Brake Assist System | CD Player |
| Car Tire Size - LR tire size P245/55WR18 | Car Tire Size - RR tire size P245/55WR18 | Car Tire Size - RF tire size P245/55WR18 |
| Car Tire Size - LF tire size P245/55WR18 | Child Safety Locks | Cruise Control |
| Cylinders - 6 | Driver Air Bag | Empty Weight - 4639 lb |
| Floor Mats | Intermittent Wipers | LED Headlights |
| LF Tires - 8/32 inch | LR Tires - 7/32 inch | MP3 Radio |
| Master Key - 2key(s) | Motor Fuel Type - Gas | Pass-Through Rear Seat |
| Pass. Air Bag | Power Brakes | Power Driver Seat |
| Power Lock | Power Mirrors | Power Steering |
| Power Windows | Privacy Glass | RF Tires - 7/32 inch |
| RR Tires - 7/32 inch | Rear Defrost | Rear Spoiler |
| Reverse Camera | Seat Trim - Cloth | Side Airbags - Front |
| Spare Tire | Steering Wheel Audio Control | Stereo - AM/FM Radio |
| Tilt Steering Wheel | Tire Brand - Front Left - LF tire mfg Goodyear | Tire Brand - Front Right - RF tire mfg Goodyear |
| Tire Brand - Rear Left - LR tire mfg Goodyear | Tire Brand - Rear Right - RR tire mfg Goodyear | Tire Pressure Monitor System |
| Traction Control | Transmission - Automatic Transmission | Trip Computer |
| Wheels Front Left - Steel | Wheels Front Right - Steel | Wheels Rear Left - Steel |
| Wheels Rear Right - Steel | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Interior | Photo Only | Estimate Only | Unknown |
|  | Photo - Wheel | Photo Only | Estimate Only | Unknown |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 4 | Photo Only | Estimate Only | Unknown |
|  | Photo - Deck | Photo Only | Estimate Only | Unknown |
|  | Photo - Vin/Id Sticker | Photo Only | Estimate Only | Unknown |
|  | Steering Wheel | Photo Only | Estimate Only | Unknown |
|  | Stereo | Photo Only | Estimate Only | Unknown |
|  | Left Rear Seat | Photo Only | Estimate Only | Unknown |
|  | Roof | Photo Only | Estimate Only | Unknown |
|  | Keys | Photo Only | Estimate Only | Unknown |
|  | Door Panels | Photo Only | Estimate Only | Unknown |
|  | Photo - Dash | Photo Only | Estimate Only | Unknown |
|  | Overall Picture - Engine | Photo Only | Estimate Only | Unknown |
|  | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 3 | Photo Only | Estimate Only | Unknown |
|  | Deck Lid Badge | Photo Only | Estimate Only | Unknown |
|  | Photo - Rear | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 2 | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 1 | Photo Only | Estimate Only | Unknown |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Dash Trim Panel | Cut | Repair | 3 To 4 Inches |
|  | Left Front Armrest | Torn | Repair | > 12 Inches |
|  | Left Front Door | Rust | Repair | 3 To 4 Inches |
|  | Left Front Fender | Chipped | Touch Up | 2 |
|  | Left Front Seat | Torn | Repair | 5 To 6 Inches |
|  | Rear Bumper/Cover | Chipped | Touch Up | 10 Or More |
|  | Right Front Door | Rust | Repair | 5 To 6 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Door | Chipped | Touch Up | 2 |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.