



Approved CR

IAA Sioux Falls
47028 276th St
Branch No 362
Sioux Falls, SD 57104
(605)271-8855/(605)271-4662
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
EXPEDITION**

Bodystyle/Series: **Sport Utility
Vehicle XL**

Color: **Black**

Mileage: **90,938
(Verified)**

Turn-in Mileage: **-**

VIN: **1FMJU1GT7LEA84061**

Work Order/
Stock Number: **45793996**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G624845X**

Vehicle Grade : **Grade 3.0**

Remarks: **-**

Announcements:

- CHECK
ENGINE
LIGHT ON

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 275 / 65 R 18

Car Tire Size - RF 275 / 65 R 18

Car Tire Size - LF 275 / 65 R 18

Car Tire Size - LR 275 / 65 R 18

LF Tires - 10/32 inch

LR Tires - 10/32 inch

RF Tires - 10/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Destination X/T

Tire Model - RF - Destination X/T


Tire Model - LR - Destination X/T

Tire Model - LF - Destination X/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Bug Damage	-	Repair Required
	Hood	Bug Damage	-	Repair Required
	Right Front Door	Multiple Scratches Light	-	3
	Right Qtr Panel	Multiple Scratches Heavy	-	4
	Rear Bumper	Broken	-	Replacement Required
	Hitchplate Cover	Missing	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.