Approved CR

America`s Auto Auction - Richmond
3600 Deepwater Terminal Road
Richmond, VA 23234
804-232-7355/804-232-1818
richmond.fleet@americasaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD FUSION HIBRIDO**
Bodystyle/Series:	**4 Door Vehicle SE 4D SEDAN FWD**
Color:	**BLUE**
Mileage:	**70,106 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**3FA6P0LU1KR149479**
Work Order/ Stock Number:	**000844332**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G120311V**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4th Passenger Door	ABS Brakes	Adaptive Cruise Control
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet
Blind Spot Monitor	Bluetooth Connection	Brake Assist System
Car Tire Size - LF tire size P225/50VR17	Car Tire Size - LR tire size P225/50VR17	Car Tire Size - RF tire size P225/50VR17
Car Tire Size - RR tire size P225/50VR17	Child Safety Locks	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Dual Air Conditioning	Electrochromic Rearview Mirror	Empty Weight - 3695 lb
Engine Immobilizer	Floor Mats	Front Wheel Drive
Front Wheel Drive	Independent Climate Control	Intermittent Wipers
Keyless Entry	Keyless Start	LF Tires - 5/32 inch
LR Tires - 6/32 inch	Lane Departure System	Master Key - 2key(s)
Motor Fuel Type - Other	Navigation System	Pass-Through Rear Seat
Pass. Air Bag	Power Brakes	Power Driver & Passenger Seat
Power Driver Seat	Power Lock	Power Mirrors
Power Steering	Power Trunk/Liftgate	Power Windows
Privacy Glass	RF Tires - 5/32 inch	RR Tires - 10/32 inch
Rain Sensor	Rear Defrost	Rear Parking Aid
Remote Trunk Release	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Michelin
Tire Brand - Front Right - RF tire mfg Michelin	Tire Brand - Rear Left - LR tire mfg Michelin	Tire Brand - Rear Right - RR tire mfg Kelly
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Multiple Scratches Heavy	Refinish	3
	Hood	Multiple Scratches Heavy	Refinish	5
	Left Rocker Panel Molding	Broken	Replace	Replacement Required
	Left Front Door	Multiple Dents/No Paint Damage	PDR	2
	Left Rear Door	Dent(S) W/No Paint Dmg	PDR	1/8 To 1/2 Inch
	Right Qtr Panel	Multiple Dents/No Paint Damage	PDR	4
	Right Front Wheel	Curb Rash	Refinish	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.