Approved CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD F-550 CHASSIS XL**
Bodystyle/Series:	**Other -**
Color:	**WHITE**
Mileage:	**87,640 (Digital)**
Turn-in Mileage:	-
VIN:	**1FDAF5GY1KDA02102**
Work Order/ Stock Number:	**0182269**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G320739V**
Vehicle Grade :	**Grade 3.1**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**10-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**6.8 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**- /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Automatic Headlights	Auxiliary Pwr Outlet	Bench Seating
Bluetooth Connection	Brake Assist System	Car LF Tires - 12/32 inch
Car LR Tires - 11/32 inch	Car RF Tires - 10/32 inch	Car RR Tires - 11/32 inch
Car Tire Size - LF: LT225/70SR19.5 LR: LT225/70SR19.5 RF: LT225/70SR19.5 RR: LT225/70SR19.5	Cylinders - 10	Daytime Running Lights
Driver Adjustable Lumbar	Dual Rear Wheels	Front Tow Hooks
Ignition Key - 2key(s)	Independent Climate Control	Intermittent Wipers
LF Tires - 12/32 inch	LR Tires - 11/32 inch	Misc. Special Features - Airbag Disconnect Switch
Mudflaps	Pass. Air Bag	Passenger Vanity Mirror
Privacy Glass	RF Tires - 10/32 inch	RR Tires - 11/32 inch
Running Board	Smart Device Integration	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire LF - 12/32 inch
Tire RF - 10/32 inch	Tire Size - LF: LT225/70SR19.5 LR: LT225/70SR19.5 RF: LT225/70SR19.5 RR: LT225/70SR19.5	Tire Size - LF: LT225/70SR19.5 LR: LT225/70SR19.5 RF: LT225/70SR19.5 RR: LT225/70SR19.5
Transmission - Automatic Transmission w/ Overdrive	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Rust	Estimate Only	4 To 5 Inches
	Oil	Low Fluid	Mechanical Check	Unacceptable
	Digital Display	Photo Only	Remove	None
[no photo]	Front Bumper	Scuffed	Estimate Only	3 To 4 Inches
[no photo]	Hood	Multiple Scratches Light	Estimate Only	4
	Left Running Board	Dent(S) W/No Paint Dmg	Estimate Only	4 To 5 Inches
	Left Qtr Panel	Scuffed	Estimate Only	> 12 Inches
	Exterior Rear Body Panel	Rust	Estimate Only	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.