Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE**
Color:	**White**
Mileage:	**14,601 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG5GR115014**
Work Order/ Stock Number:	**46424716**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G414760Z**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 65 R 17	Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17
Car Tire Size - RF 225 / 65 R 17	LF Tires - 9/32 inch	LR Tires - 11/32 inch
RF Tires - 9/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - SUREDRIVE
Tire Brand - Front Right - SUREDRIVE	Tire Brand - Rear Left - SUREDRIVE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - RR - All-Season	Tire Model - RF - All-Season	Tire Model - LR - All-Season
Tire Model - LF - All-Season		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Rf Strut	Rust	-	Severe Damage
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	4
	Right Front Wheel Cover	Curb Rash	-	1 To 2 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel Cover	Peeling	-	2 To 3 Inches
	Rear Bumper	Chipped	-	3
	Left Rear Wheel Cover	Peeling	-	9 To 10 Inches
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Peeling	-	9 To 10 Inches
	Shifter Knob	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door Handle	Heavy Scratch	-	1 To 2 Inches
	Rear Bumper Step Pad	Bent	-	Replacement Required
	Right Front Door Handle	Chipped	-	4
	Right Rear Door Handle	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.