Approved CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT-350**
Bodystyle/Series:	**3 Door Wagon XL**
Color:	**WHITE**
Mileage:	**65,046 (Digital)**
Turn-in Mileage:	-
VIN:	**1FBZX2ZM4JKB42933**
Work Order/ Stock Number:	**0181346**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G433419U**
Vehicle Grade :	**Grade 3.1**
Remarks:	-
Announcements:	• 5TH ROW SEAT MISSING
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

3rd Row Seat	Auxiliary Audio Input	Auxiliary Pwr Outlet
Backup camera and monitor	Bluetooth Connection	Brake Assist System
Car LF Tires - 11/32 inch	Car LR Tires - 6/32 inch	Car RF Tires - 11/32 inch
Car RR Tires - 5/32 inch	Car Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16 SP: FULL SIZE	Cylinders - 6
Daytime Running Lights	Driver Adjustable Lumbar	Driver Illuminated Vanity Mirr
Driver Vanity Mirror	Electronic Stability Control	Floor Mats
Front Head Air Bag	Ignition Key - 1key(s)	Independent Climate Control
Intermittent Wipers	Keyless Entry - Left	LF Tires - 11/32 inch
LR Tires - 6/32 inch	Leather Steering Wheel	MP3 Radio
Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Illuminated Vanity M	Passenger Vanity Mirror	Power Mirrors
Privacy Glass	RF Tires - 11/32 inch	RR Tires - 5/32 inch
Rear AC	Rear Bench Seat	Rear Head Air Bag
Side Airbags - Front	Smart Device Integration	Spare Tire - Full Size
Spare Tire Tread - 11/32 inch	Spare Wheel - Steel	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire LF - 11/32 inch
Tire Pressure Monitor System	Tire RF - 11/32 inch	Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16 SP: FULL SIZE
Tire Size - LF: LT235/65SR16 LR: LT235/65SR16 RF: LT235/65SR16 RR: LT235/65SR16 SP: FULL SIZE	Transmission - Automatic Transmission w/ Overdrive	Trip Computer
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel	WiFi Hotspot	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	5th Row Seat	Missing	Estimate Only	Replacement Required
	Right Rear Seat	Worn	Estimate Only	Replacement Required
	Right Seat Back 4th Row	Worn	Estimate Only	Replacement Required
	Right 3rd Row Leanback	Worn	Estimate Only	Replacement Required
	Digital Display	Photo Only	Remove	None
[no photo]	Right Rear Door	Multiple Scratches Light	Estimate Only	4
	Rear Door	De-Identify	De-Identify	Removal Required
	Left Qtr Panel	Dent(S) W/ Paint Dmg	Estimate Only	> 12 Inches
	Windshield	Cracked	Replace	1/2 To 1 Inch
[no photo]	Hood	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.