



Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2011 FORD
F-250**
2 Door
Bodystyle/Series: **Vehicle XL
REG CAB**
Color: **WHITE**
Mileage: **29,321
(Exempt, 6
digits)**
Turn-in Mileage: -
VIN: **1FDBF2A65BEC76231**
Work Order/
Stock Number: **000116837**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: -
Vehicle Grade : **Grade 4.3**
AutoGrade : **4.3 - Clean**
Remarks: -
Announcements: -
Certification : **Not Certified**
Req. Prev. Repair
Order: -



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	No
Interior - Type/Color:	Vinyl Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

ABS Brakes	Auxiliary Pwr Outlet	Bench Seating
Brake Assist System	CD Player	Car Tire Size - RF tire size LT245/75SR17
Car Tire Size - RR tire size LT245/75SR17	Car Tire Size - LR tire size LT245/75SR17	Car Tire Size - LF tire size LT245/75SR17
Cylinders - 8	Daytime Running Lights	Driver Air Bag
Empty Weight - 5855 lb	Engine Immobilizer	Intermittent Wipers
LF Tires - 7/32 inch	LR Tires - 9/32 inch	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Lock	Power Steering
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 9/32 inch
Rear View Mirror	Seat Trim - Vinyl	Side Airbags - Front
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Cooper	Tire Brand - Front Right - RF tire mfg Cooper
Tire Brand - Rear Left - LR tire mfg Kelly	Tire Brand - Rear Right - RR tire mfg Kelly	Tire Pressure Monitor System
Tow Hitch	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Two-Wheel Drive	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Multiple Dents/Paint Damage	Repair	2
	Right Front Door	Chipped	Touch Up	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Left Rocker Panel	Chipped	Touch Up	4
	Left Front Door	Chipped	Touch Up	5
	Left Front Fender	Chipped	Touch Up	2
	R Cab Corner Panel	Multiple Dents/No Paint Damage	PDR	Pdr-4 Dents
	Rear Bumper/Cover	Multiple Scratches Heavy	Refinish	6

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.