



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 KIA
NIRO**
Bodystyle/Series: **4 Door Sport
Utility Vehicle
FE 4D SUV
FWD**
Color: **GRAY**
Mileage: **95,587
(Verified, 6
digits)**
Turn-in Mileage: **-**
VIN: **KNDCB3LCXJ5186908**
Work Order/
Stock Number: **000081833**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G413792V**
Vehicle Grade : **Grade 4.4**
Remarks: **-**

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION
- HOWEVER, THE ABSENCE OF ANY INDICATED DEFICIENCIES
- DOES NOT MEAN THERE ARE NONE.

Certification : **Not Certified**
Req. Prev. Repair
Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
---------------	------------------------	------	-----

Equipment			
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Bluetooth Connection	Brake Assist System	Car Tire Size - LR tire size P205/60HR16	
Car Tire Size - RR tire size P205/60HR16	Car Tire Size - RF tire size P205/60HR16	Car Tire Size - LF tire size P205/60HR16	
Child Safety Locks	Cruise Control	Cylinders - 4	
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning	
Empty Weight - 3106 lb	Engine Immobilizer	Floor Mats	
Front Wheel Drive	Front Wheel Drive	Hard Disk Drive Media Storage	
Independent Climate Control	Intermittent Wipers	Keyless Entry	
LF Tires - 8/32 inch	LR Tires - 8/32 inch	MP3 Radio	
Master Key - 1key(s)	Motor Fuel Type - Other	Pass-Through Rear Seat	
Pass. Air Bag	Power Brakes	Power Lock	
Power Mirrors	Power Steering	Power Windows	
Privacy Glass	RF Tires - 8/32 inch	RR Tires - 9/32 inch	
Rear Defrost	Rear Spoiler	Reverse Camera	
Seat Trim - Cloth	Security System	Side Airbags - Front	
Steering Wheel Audio Control	Stereo - AM/FM Radio	Telematics	
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg GOOD YEAR	Tire Brand - Front Right - RF tire mfg GOOD YEAR	
Tire Brand - Rear Left - LR tire mfg GOOD YEAR	Tire Brand - Rear Right - RR tire mfg GOOD YEAR	Tire Pressure Monitor System	
Traction Control	Transmission - Automatic Transmission	Trip Computer	
XM Radio			

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper/Cover	Chipped	Report	5
	Rear Bumper/Cover	Multiple Scratches Heavy	Report	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Drip Rail	Multiple Scratches Light	Report	6
	Right Rear Door	Scuffed	Report	2 To 3 Inches
	Windshield	Star In Glass	Replace	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.