



Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-350**
Bodystyle/Series: **Extended Cab
XL**
Color: **White**
Mileage: **64,610
(Verified)**
Turn-in Mileage: **-**
VIN: **1FD8X3B66HED80960**
Work Order/
Stock Number: **46411327**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632892U**
Vehicle Grade : **Grade 1.6**
Remarks: **-**
Announcements:

- Rust
/Corrosion

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17

Car Tire Size - LR 245 / 75 R 17

Car Tire Size - RR 245 / 75 R 17

Car Tire Size - RF 245 / 75 R 17

LF Tires - 9/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 7/32 inch

Tire Brand - Front Left - KELLY

Tire Brand - Front Right - KELLY

Tire Brand - Rear Left - KELLY

Tire Brand - Rear Right - KELLY

Tire Model - RR - Edge A/T

Tire Model - RF - Edge A/T

Tire Model - LR - Edge A/T

Tire Model - LF - Edge A/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Right Front Inter. Door Handle	Worn	-	Replacement Required

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Acceptable
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Multiple Dents/Paint Damage	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	3 To 4 Inches
	Right Bed Side	Multiple Scratches Heavy	-	3
	Right Rear Wheel	Corrosion	-	3 To 4 Inches
	Tailgate	Rust	-	> 12 Inches
	Exterior Rear Body Panel	Multiple Scratches Heavy	-	3
	Left Bed Side	Multiple Scratches Heavy	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Left Front Fender	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.