Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 FORD F-650 DIESEL KICK-UP**
Bodystyle/Series:	- -
Color:	**White**
Mileage:	**1 (Unverified)**
Turn-in Mileage:	-
VIN:	**1FDNF6EC6HDB12036**
Work Order/ Stock Number:	**46100478**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710773U**
Vehicle Grade :	**Grade 0.0**
Remarks:	-
Announcements:	• JUNK TITLE • PARTS ONLY!! • NOT TO BE TITLED FOR HWY USE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	**3rd**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 70 R 19	Car Tire Size - RF 245 / 70 R 19	Car Tire Size - LF 245 / 70 R 19
Car Tire Size - LR 245 / 70 R 19	LF Tires - 17/32 inch	LR Tires - 16/32 inch
RF Tires - 17/32 inch	RR Tires - 18/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - DOUBLE COIN	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - DOUBLE COIN
Tire Model - LF - Smart Flex AH35	Tire Model - LR - Smart Flex AH35	Tire Model - RF - Double Coin RLB490
Tire Model - RR - Double Coin RLB490		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Mirror	Broken	-	Replacement Required
	Left Front Fender	Missing	-	Replacement Required
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Left Front Tire	Flat	-	Repair Required
	Roof	Rust	-	> 12 Inches
	Right Front Seat	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat	Broken	-	Replacement Required
	Steering Wheel	Missing	-	Replacement Required
	Windshield	Missing	-	Replacement Required
	Radio	Missing	-	Replacement Required
	Dash	Missing	-	Replacement Required
	Dash Cluster	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Headlining	Missing	-	Replacement Required
	Left Sunvisor	Missing	-	Replacement Required
	Right Sunvisor	Missing	-	Replacement Required
	Climate Control Panel	Missing	-	Replacement Required
	Front Metal Bumper Painted	Rust	-	> 12 Inches
	Cargo Box Front Wall	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Severe Damage	-	Replacement Required
	Right Mirror	Missing	-	Replacement Required
	Right Front Fender	Missing	-	Replacement Required
	Hood	Missing	-	Replacement Required
	Right Head Lamp	Missing	-	Replacement Required
	Left Head Lamp	Missing	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Radiator	Broken	-	Replacement Required
	Right Running Board	Bent	-	2 To 3 Inches
	Right Front Tire	Worn	-	Replacement Required
	Right Cab Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Cargo Box Right Side Wall	Broken	-	Replacement Required
	Right Rear Wheel	Corrosion	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Exterior Rear Body Panel	Multiple Scratches Heavy	-	5
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Door	Severe Damage	-	Replacement Required
	Cab - Left	Severe Damage	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.