Approved
CR

IAA Fargo
4401 37th St. N
Branch No 363
Fargo, ND 58102
(701)552-9731/(701)552-9736
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2024 FORD F-350 CHASSIS**
Bodystyle/Series:	**Regular Cab XL/XLT**
Color:	**White**
Mileage:	**1 (Unverified)**
Turn-in Mileage:	-
VIN:	**1FDRF3HT7REC59117**
Work Order/ Stock Number:	**45419728**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G310125Z**
Vehicle Grade :	**Grade 0.0**
Remarks:	-
Announcements:	• COLLISION DAMAGE • LAST KNOWN MILEAGE 69346 • UNECONOMICAL TO REPAIR - NON DRIVEABLE
Certification :	-
Req. Prev. Repair Order:	-

Drivable: No

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- /-	Rear Defroster:	**No**
Airbag:	-	Tilt Steering:	**No**
Seats:	-	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: -


Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 12/32 inch	LR Tires - 1/32 inch
RF Tires - 12/32 inch	RR Tires - 2/32 inch	Tire Brand - Front Left - LAUFENN
Tire Brand - Front Right - LAUFENN	Tire Brand - Rear Left - LAUFENN	Tire Brand - Rear Right - LAUFENN
Tire Model - RR - X Fit HT (LD01)	Tire Model - RF - X Fit HT (LD01)	Tire Model - LR - X Fit HT (LD01)
Tire Model - LF - X Fit HT (LD01)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Center Console	Aftermarket	-	Acceptable
	Right Front Fender	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Box Left Side Wall	Heavy Scratch	-	> 12 Inches
	Left Front Fender	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	6 To 7 Inches
	Cargo Box Right Side Wall	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Rear Tire	Worn	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required
	Windshield	Cracked	-	> 12 Inches
	Left Side Curtain Air Bag	Deployed	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Curtain Air Bag	Deployed	-	Replacement Required
	Lf Seat Air Bag	Deployed	-	Replacement Required
	Rf Seat Air Bag	Deployed	-	Replacement Required
	Left Mirror	Missing	-	Replacement Required
	Left Front Door	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Rear Wheel	Rust	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Grille	Broken	-	Replacement Required
	Left Head Lamp	Faded	-	Repair Required
	Left Front Wheel	Bent	-	Replacement Required
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.