Approved CR

IAA Savannah
348 Commerce Dr.
Branch No 704
Rincon, GA 31326
(912) 826-1219/(912) 826-1387
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 CHEVROLET SILVERADO 1500**
Bodystyle/Series:	**- WT**
Color:	**Silver**
Mileage:	**24,526 (Verified)**
Turn-in Mileage:	-
VIN:	**1GCNKNEH6GZ244673**
Work Order/ Stock Number:	**46460728**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G620482S**
Vehicle Grade :	**Grade 3.4**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**4.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Air Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 255 / 70 R 17	Car Tire Size - LR 255 / 70 R 17	Car Tire Size - RR 255 / 70 R 17
Car Tire Size - RF 255 / 70 R 17	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - LAUFENN	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - STARFIRE
Tire Model - LF - Dueler H/T	Tire Model - RR - Solarus HT	Tire Model - RF - X Fit At (LC01)
Tire Model - LR - Dueler H/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Right Tail Light	Broken	-	Replacement Required
	Inside Bed	Multiple Scratches Heavy	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Multiple Scratches Heavy	-	2
	Front Bumper	Chipped	-	1

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.