Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2017 RAM 1500** |
| Bodystyle/Series: | **2 Door Pickup Truck ST** |
| Color: | **WHITE** |
| Mileage: | **41,878 (Verified, 6 digits)** |
| Turn-in Mileage: | - |
| VIN: | **3C6JR7AG4HG585226** |
| Work Order/ Stock Number: | **000312502** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G62-5550S** |
| Vehicle Grade : | **Grade 3.4** |
| Remarks: | - |
| Announcements: | • DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER,<br>• THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE NONE |
| Certification : | **Not Certified** |
| Req. Prev. Repair Order: | - |

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **Yes** |
| Engine: | **6-Cylinder Flex Fuel** | Cruise Control: | **No** |

## Equipment

| | | | |
|---|---|---|---|
| Engine Size: | **3.6 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **No** |
| Radio: | - | Pwr Windows | **No** |
| Interior - Type/Color: | - **/GRAY** | Rear Defroster: | **No** |
| Airbag: | **Dual Air Bags** | Tilt Steering: | **Yes** |
| Seats: | - | Drive Type: | **4-Wheel Drive** |
| Seat Count: | - | Brakes: | **Power Brakes** |

Additional Equipment:

| | | |
|---|---|---|
| 4 Wheel Drive | Air Conditioning | LF Tires - 12/32 inch |
| LR Tires - 10/32 inch | Power Brakes | Power Steering |
| RF Tires - 12/32 inch | RR Tires - 10/32 inch | Security System |
| Tilt Wheel | Tire Brand - Front Left - LF TIRE MFG Goodyear | Tire Brand - Front Right - RF TIRE MFG Goodyear |
| Tire Brand - Rear Left - LR TIRE MFG Goodyear | Tire Brand - Rear Right - RR TIRE MFG Goodyear | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Left | Photo Only | Estimate Only | Unknown |
|  | Photo - Right | Photo Only | Estimate Only | Unknown |
|  | Photo - Front | Photo Only | Estimate Only | Unknown |
|  | Overall Picture - Engine | Photo Only | Estimate Only | Unknown |
|  | Frame | Photo Only | Estimate Only | Unknown |
|  | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown |
|  | Rear Bumper | Rust | Report | Permanent |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Fender | Scuffed | Report | Buffable |
|  | Vin Plate | Photo Only | Estimate Only | Unknown |
|  | Photo - Interior | Photo Only | Estimate Only | Unknown |
|  | Photo - Wheel | Photo Only | Estimate Only | Unknown |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Front Door | Dent(S) W/ Paint Dmg | PDR | Pdr-1 Dent |
| [no photo] | Warning Light - Brakes | Worn | Replace | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.