



Approved CR

IAA Reno
4086 Peru Drive
Branch No 154
McCarran, NV 89434
(775) 636-8829/(775) 636-7280
WHOLESALE ASSESSMENT ONLY

2019
CHEVROLET
Make/Model: **EXPRESS**
CUTAWAY
4500
Bodystyle/Series: - -
Color: **White**
Mileage: **85,909**
(Verified)
Turn-in Mileage: -
VIN: **1GB0GRFP2K1371179**
Work Order/
Stock Number: **46424916**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: **G43-1990W**
Vehicle Grade : **Grade 3.8**
Remarks: -
Announcements: -
Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment


Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Leather Interior /TAN	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Sport	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 16	Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 10/32 inch	LR Tires - 14/32 inch
RF Tires - 9/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - HERCULES
Tire Brand - Front Right - HERCULES	Tire Brand - Rear Left - HERCULES	Tire Brand - Rear Right - HERCULES
Tire Model - RR - Terra Trac CH4	Tire Model - RF - Terra Trac CH4	Tire Model - LR - Terra Trac CH4
Tire Model - LF - Terra Trac CH4		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper Step Pad	Bent	-	Replacement Required
	Left Front Seat Cushion	Torn	-	3 To 4 Inches
	Headlining	Cut	-	1 To 2 Inches
	Steering Wheel	Worn	-	Replacement Required
	Front Metal Bumper Painted	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.