



Approved CR

IAA Missoula
10131 Garrymore Lane
Branch No 360
Missoula, MT 59802
(406) 542-3442/(406) 549-8933
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
SILVERADO
1500**

Bodystyle/Series: **Regular Cab
WT**

Color: **Gray**

Mileage: **33,221
(Verified)**

Turn-in Mileage: **-**

VIN: **1GCNCNEH4GZ240926**

Work Order/
Stock Number: **46357364**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**

Client Stock #: **G420672S**

Vehicle Grade : **Grade 3.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	4.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 255 / 70 R 17	Car Tire Size - RR 255 / 70 R 17	Car Tire Size - RF 255 / 70 R 17
Car Tire Size - LF 255 / 70 R 17	LF Tires - 6/32 inch	LR Tires - 9/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - COOPER	Tire Brand - Rear Right - COOPER
Tire Model - LF - Discoverer Rugged Trek	Tire Model - LR - ruf	Tire Model - RF - ruf
Tire Model - RR - ruf		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Multiple Dents/No Paint Damage	-	2
	Cab - Left	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Left Drip Rail	Multiple Dents/No Paint Damage	-	3
	Grille - Chrome	Chipped	-	1
	Right Bed Side	Dent(S) W/ Paint Dmg	-	2 To 3 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Torn	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	1/2 To 1 Inch
	Tailgate	Multiple Dents/Paint Damage	-	2
	Rear Metal Bumper Painted	Chipped	-	8
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Hood	Multiple Scratches Heavy	-	2
	Front Metal Bumper Painted	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.