Approved
CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD POLICE INTERCEPTOR U**
Bodystyle/Series:	**Sport Utility Vehicle -**
Color:	**WHITE**
Mileage:	**46,317 (Digital)**
Turn-in Mileage:	-
VIN:	**1FM5K8AR4JGC56531**
Work Order/ Stock Number:	**0182859**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**112615I1C56531**
Vehicle Grade :	**Grade 2.7**
Remarks:	-
Announcements:	• Previous police vehicle • PRIOR POLICE - INTERIOR/EXTERIOR DAMAGE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**CD Only**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**All Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4th Passenger Door	Adjustable Pedals	Auxiliary Audio Input
Auxiliary Pwr Outlet	Backup camera and monitor	Bluetooth Connection
Brake Assist System	Car LF Tires - 5/32 inch	Car LR Tires - 6/32 inch
Car RF Tires - 6/32 inch	Car RR Tires - 6/32 inch	Car Tire Size - LF: P245/55WR18 LR: P245/55WR18 RF: P245/55WR18 RR: P245/55WR18 SP: FULL SIZE
Child Safety Locks	Cylinders - 6	Driver Adjustable Lumbar
Driver Vanity Mirror	Electrochromic Rearview Mirror	Electronic Stability Control
Fog Lamps	Front Head Air Bag	Ignition Key - 1key(s)
Independent Climate Control	Intermittent Wipers	LED Headlights
LF Tires - 5/32 inch	LR Tires - 6/32 inch	MP3 Radio
Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Vanity Mirror	Power Driver Seat	Power Mirrors
Power Trunk/Liftgate	Privacy Glass	RF Tires - 6/32 inch
RR Tires - 6/32 inch	Rear AC	Rear Bench Seat
Rear Head Air Bag	Rear Spoiler	Remote Trunk Release
Side Airbags - Front	Spare Tire - Full Size	Spare Tire Tread - 6/32 inch
Spare Wheel - Steel	Steering Wheel Audio Control	Tilt Steering Wheel
Tire LF - 5/32 inch	Tire Pressure Monitor System	Tire RF - 6/32 inch
Tire Size - LF: P245/55WR18 LR: P245/55WR18 RF: P245/55WR18 RR: P245/55WR18 SP: FULL SIZE	Tire Size - LF: P245/55WR18 LR: P245/55WR18 RF: P245/55WR18 RR: P245/55WR18 SP: FULL SIZE	Transmission - Automatic Transmission w/ Overdrive
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Left Fog Lamp	Hole(S)	Estimate Only	Replacement Required
[no photo]	Right Fog Lamp	Hole(S)	Estimate Only	Replacement Required
	Left Head Lamp	Hole(S)	Estimate Only	Replacement Required
	Right Head Lamp	Hole(S)	Estimate Only	Replacement Required
[no photo]	Hood	Scuffed	Estimate Only	2 To 3 Inches
[no photo]	Left Front Door	Multiple Scratches Light	Estimate Only	5

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Left Front Weather Strip	Torn	Estimate Only	Replacement Required
	Roof	Hole(S)	Estimate Only	3 To 4 Inches
	Center Console	Aftermarket	De-Identify	Removal Required
	Digital Display	Photo Only	Remove	None
	Left Front Door Panel	Cracked	Estimate Only	Replacement Required
	Headlining	Hole(S)	Estimate Only	2 To 3 Inches
[no photo]	Left Rear Door Panel	Missing	Estimate Only	Replacement Required
[no photo]	Right Rear Door Panel	Missing	Estimate Only	Replacement Required
[no photo]	Right Rear Seat Back	Aftermarket	-	Acceptable
[no photo]	Left Front Fender	Multiple Scratches Light	Estimate Only	4
	Left A Pillar	Multiple Holes	Estimate Only	4
[no photo]	Left Brake Light	Hole(S)	Estimate Only	Replacement Required
	Left Rear Door	Multiple Scratches Heavy	Estimate Only	6
[no photo]	Left Qtr Panel	Multiple Scratches Light	Estimate Only	3
	Rear Bumper	Multiple Scratches Heavy	Estimate Only	5
	Rear Door	Dent(S) W/No Paint Dmg	Estimate Only	9 To 10 Inches
[no photo]	Right Brake Light	Hole(S)	Estimate Only	Replacement Required
[no photo]	Right Rear Door	Multiple Scratches Heavy	Estimate Only	2
	Right Front Door	Multiple Dents/Paint Damage	Estimate Only	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Dent(S) W/ Paint Dmg	Estimate Only	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.