



Approved CR

IAA Sioux Falls
47028 276th St
Branch No 362
Sioux Falls, SD 57104
(605)271-8855/(605)271-4662
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
CHEVROLET
EQUINOX**
Bodystyle/Series: **Sport Utility
Vehicle AWD
LS**
Color: **Silver**
Mileage: **112,793
(Verified)**
Turn-in Mileage: **-**
VIN: **3GNAXSEV3LS724804**
Work Order/
Stock Number: **45964608**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G611702X**
Vehicle Grade : **Grade 3.3**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17

Car Tire Size - RF 225 / 65 R 17

Car Tire Size - LF 225 / 65 R 17

Car Tire Size - LR 225 / 65 R 17

LF Tires - 5/32 inch

LR Tires - 6/32 inch

RF Tires - 4/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - OTANI

Tire Brand - Front Right - OTANI

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - OTANI

Tire Model - LF - SA1000

Tire Model - LR - Destination LE2

Tire Model - RF - SA1000

Tire Model - RR - SA1000

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper Cover Upper	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	2 To 3 Inches
	Windshield	Cracked	-	> 12 Inches
	Right Rear Tire	Worn	-	Replacement Required
	Lift Gate	Dent(S) W/ Paint Dmg	-	3 To 4 Inches
	Front Bumper	Chipped	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.