Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD TRANSIT**
Bodystyle/Series:	**Van T-150**
Color:	**RED**
Mileage:	**74,057 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FMZK1ZM7JKB52677**
Work Order/ Stock Number:	**000311502**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G42-2445V**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	• DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER • THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE NONE
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**3.7 L**	Pwr Steering:	**Yes**


Equipment

Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	- **/BLACK**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Additional Equipment:

Air Conditioning	LF Tires - 3/32 inch	LR Tires - 2/32 inch
Power Brakes	Power Steering	Power Windows
RF Tires - 3/32 inch	RR Tires - 2/32 inch	Security System
Tilt Wheel	Tire Brand - Front Left - LF TIRE MFG Goodyear	Tire Brand - Front Right - RF TIRE MFG Goodyear
Tire Brand - Rear Left - LR TIRE MFG Goodyear	Tire Brand - Rear Right - RR TIRE MFG Goodyear	Two-Wheel Drive


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Vin Plate	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Left	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Repair	Unknown
	Left Qtr Panel	Ding	PDR	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.