



Original
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 CHEVROLET
COLORADO**
Bodystyle/Series: - -
Color: **Black**
Mileage: **18,557 (Verified)**
Turn-in Mileage: -
VIN: **1GCGSBEAXH1266945**
Work Order/
Stock Number: **46435225**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: **G410381U**
Vehicle Grade : **Grade 3.6**
Remarks: -
Announcements: **• ANNOUNCEMENTS:**
Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	-	A/C:	Yes
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 70 R 16

Car Tire Size - LR 265 / 70 R 16

Car Tire Size - RR 265 / 70 R 16

Car Tire Size - RF 265 / 70 R 16

LF Tires - 11/32 inch

LR Tires - 11/32 inch

RF Tires - 11/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - KUMHO

Tire Brand - Front Right - KUMHO

Tire Brand - Rear Left - KUMHO

Tire Brand - Rear Right - KUMHO

Tire Model - RR - Crugen HT51

Tire Model - RF - Crugen HT51


Tire Model - LR - Crugen HT51

Tire Model - LF - Crugen HT51

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Tailgate	Heavy Scratch	-	> 12 Inches
	Left Bed Side	Heavy Scratch	-	1 To 2 Inches
	Left Front Door	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Fender	Heavy Scratch	-	1/2 To 1 Inch
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Front Bumper	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.