Approved CR

IAA Albuquerque
4400 Broadway Blvd SE
Branch No 140
Albuquerque, NM 87105
(505) 873-2081/(505) 873-3029
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 JEEP CHEROKEE**
Bodystyle/Series:	**Sport Utility Vehicle SPORT**
Color:	**White**
Mileage:	**25,750 (Verified)**
Turn-in Mileage:	-
VIN:	**1C4PJMAB1GW313939**
Work Order/ Stock Number:	**46426622**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G61-1967S**
Vehicle Grade :	**Grade 4.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment


Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.4 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /-**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 9/32 inch	LR Tires - 10/32 inch
RF Tires - 8/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - NATIONAL
Tire Brand - Front Right - NATIONAL	Tire Brand - Rear Left - NATIONAL	Tire Brand - Rear Right - NATIONAL
Tire Model - LF - Commando HTS	Tire Model - LR - Commando HTS	Tire Model - RF - Commando HTS
Tire Model - RR - Commando HTS		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Seat Cushion	Stained	-	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY,

WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.