Approved CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2015 FORD F-550 CHASSIS**
Bodystyle/Series:	**Extended Cab XL**
Color:	**White**
Mileage:	**151,583 (Verified)**
Turn-in Mileage:	-
VIN:	**1FD0X5HT5FEA04740**
Work Order/ Stock Number:	**46426834**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G710814Y**
Vehicle Grade :	**Grade 1.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RF 245 / 70 R 19.5	Car Tire Size - LR 245 / 70 R 19.5	Car Tire Size - RR 245 / 70 R 19.5
Car Tire Size - LF 245 / 70 R 19.5	LF Tires - 11/32 inch	LR Tires - 9/32 inch
RF Tires - 11/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - Zomax
Tire Brand - Front Right - Zomax	Tire Brand - Rear Left - Zomax	Tire Brand - Rear Right - zomax
Tire Model - LF - founders	Tire Model - LR - founders	Tire Model - RR - founders
Tire Model - RF - founders		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Aftermarket	-	Acceptable
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Left Running Board	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Front Metal Bumper Painted	Multiple Scratches Heavy	-	8

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Right Rear Door	Multiple Dents/Paint Damage	-	2
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Bed Side	Rust	-	> 12 Inches
	Tailgate	Multiple Scratches Heavy	-	10 Or More
	Left Bed Side	Rust	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Door	Chipped	-	10 Or More
	Cab - Left	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Seat Cushion	Torn	-	1 To 2 Inches
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Lf Mirror Cover	Broken	-	Replacement Required
	Exterior Rear Body Panel	Rust	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.