Approved CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 RAM 3500**
Bodystyle/Series:	**Crew Cab TRADESMAN 4X4 6`4 BOX**
Color:	**White**
Mileage:	**59,355 (Verified)**
Turn-in Mileage:	-
VIN:	**3C63R3CT5JG386994**
Work Order/ Stock Number:	**46426783**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G632411V**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**No**
Engine Size:	**5.7 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 70 R 18	Car Tire Size - LR 275 / 70 R 18	Car Tire Size - RR 275 / 70 R 18
Car Tire Size - RF 275 / 70 R 18	LF Tires - 17/32 inch	LR Tires - 17/32 inch
RF Tires - 17/32 inch	RR Tires - 17/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Wildpeak A/T4W	Tire Model - RF - Wildpeak A/T4W	Tire Model - LR - Wildpeak A/T4W
Tire Model - LF - Wildpeak A/T4W		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Running Board	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	3
	Right Front Fender	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Rocker Panel	Chipped	-	2
	Right Rear Wheel	Corrosion	-	1 To 2 Inches
	Rear Metal Bumper Painted	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Chipped	-	1
	Left Bed Side	Light Scratch	-	1 To 2 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.