Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 DODGE GRAND CARAVAN**
Bodystyle/Series:	**Van SE**
Color:	**White**
Mileage:	**81,183 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RDGBG1JR318649**
Work Order/ Stock Number:	**46499062**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G412111V**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - BFGOODRICH
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - BFGOODRICH	Tire Brand - Rear Right - BFGOODRICH
Tire Model - RR - Advantage Control	Tire Model - RF - Advantage Control	Tire Model - LR - Advantage Control
Tire Model - LF - Advantage Control		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Heavy Scratch	-	4 To 5 Inches
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.