



Approved
CR

United Auto Exchange
3710 Prescott Rd
Memphis, TN 38118
9017957634
jcraig@uaxmemphis.com
WHOLESALE ASSESSMENT ONLY

Make/Model: 2020
HYUNDAI
IONIQ
HYBRID
4 Door Sedan
Bodystyle/Series: BLUE 4D
HATCHBACK
Color: SILVER
Mileage: 98,376
(Verified, 6
digits)
Turn-in Mileage: -
VIN: KMHC65LC8LU232143
Work Order/
Stock Number: 000083860
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: G132522X
Vehicle Grade : Grade 3.6
Remarks: -

Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION
- HOWEVER, THE ABSENCE OF ANY INDICATED DEFICIENCIES
- DOES NOT MEAN THERE ARE NONE

Certification : Not Certified
Req. Prev. Repair -
Order:



Drivable: Yes


UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Equipment			
Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	Automatic Headlights	
Bluetooth Connection	Brake Assist System	Car Tire Size - RR tire size 195/65R15	
Car Tire Size - LR tire size 195/65R15	Car Tire Size - LF tire size 195/65R15	Car Tire Size - RF tire size 195/65R15	
Child Safety Locks	Collision Avoidance	Cruise Control	
Cylinders - 4	Daytime Running Lights	Driver Air Bag	
Dual Air Conditioning	Empty Weight - 2996 lb	Engine Immobilizer	
Floor Mats	Front Wheel Drive	Front Wheel Drive	
Independent Climate Control	Intermittent Wipers	Keyless Entry	
Keyless Start	LF Tires - 4/32 inch	LR Tires - 7/32 inch	
Lane Departure System	MP3 Radio	Master Key - 1key(s)	
Motor Fuel Type - Other	Pass-Through Rear Seat	Pass. Air Bag	
Power Brakes	Power Lock	Power Mirrors	
Power Steering	Power Windows	RF Tires - 5/32 inch	
RR Tires - 7/32 inch	Rear Defrost	Rear Spoiler	
Reverse Camera	Seat Trim - Cloth	Security System	
Side Airbags - Front	Steering Wheel Audio Control	Stereo - AM/FM Radio	
Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg GOOD YEAR	Tire Brand - Front Right - RF tire mfg SOLARUS	
Tire Brand - Rear Left - LR tire mfg GOOD YEAR	Tire Brand - Rear Right - RR tire mfg GOOD YEAR	Tire Pressure Monitor System	
Traction Control	Transmission - Automatic Transmission	Trip Computer	
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium	
Wheels Rear Right - Aluminium			


Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper Cen. Molding	Cracked	Report	2 To 3 Inches
	Front Bumper/Cover	Chipped	Report	10 Or More

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Multiple Dents/Paint Damage	Report	3
	Left Drip Rail	Dent(S) W/ Paint Dmg	Report	1/2 To 1 Inch
	Left Front Seat Cushion	Stained	Report	Permanent
	Left Rear Door	Multiple Dents/Paint Damage	Report	2
	Left Rear Seat Cushion	Stained	Report	Permanent
	Rear Bumper/Cover	Heavy Scratch	Report	1 To 2 Inches
	Deck Lid	Enviro Paint Damage	Report	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.