



Approved CR

IAA Houston South
2839 E FM 1462
Branch No 414
Rosharon, TX 77583
(281)369-1010/(833)246-9256
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 CHEVROLET TAHOE**
Bodystyle/Series: **Sport Utility Vehicle 2WD LS**
Color: **Silver**
Mileage: **100,424 (Verified)**
Turn-in Mileage: **-**
VIN: **1GNSCAEC5LR107500**
Work Order/
Stock Number: **46378840**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **D41-D6650**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 265 / 65 R 18

Car Tire Size - LR 265 / 65 R 18

Car Tire Size - RR 265 / 65 R 18

Car Tire Size - RF 265 / 65 R 18

LF Tires - 9/32 inch

LR Tires - 9/32 inch

RF Tires - 9/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - PATHFINDER

Tire Brand - Front Right - PATHFINDER

Tire Brand - Rear Left - PATHFINDER

Tire Brand - Rear Right - PATHFINDER

Tire Model - RR - Pathfinder HT

Tire Model - RF - Pathfinder HT

Tire Model - LR - Pathfinder HT

Tire Model - LF - Pathfinder HT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Lift Gate	Chipped	-	3
	Hitchplate Cover	Missing	-	Replacement Required
	Right Rear Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Right Qtr Panel	Multiple Dents/No Paint Damage	-	2
	Hood	Chipped	-	3
	Front Bumper	Chipped	-	7

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.