



Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE
GRAND
CARAVAN**

Bodystyle/Series: **Van SE**

Color: **Gray**

Mileage: **41,090
(Verified)**

Turn-in Mileage: **-**

VIN: **2C4RDGBG9KR520382**

Work Order/
Stock Number: **46378769**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G414625V**

Vehicle Grade : **Grade 4.2**

Remarks: **-**

Announcements:

- Warning light. Power window issue

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RF 225 / 55 R 17

Car Tire Size - LF 225 / 55 R 17

Car Tire Size - RR 225 / 55 R 17

Car Tire Size - LR 225 / 55 R 17

LF Tires - 6/32 inch

LR Tires - 9/32 inch

RF Tires - 5/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR

Tire Model - LF - Assurance

Tire Model - RR - Assurance




Tire Model - RF - Assurance

Tire Model - LR - Assurance

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Heavy Scratch	-	1 To 2 Inches
	Right Rocker Panel Molding	Gouged	-	1 To 2 Inches
	Hood	Chipped	-	5

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.