



Approved CR

IAA Metro DC
14149 Brandywine Rd
Brandywine, MD 20613
(301) 372-8876/(301) 372-8285
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
POLICE
INTERCEPTOR**

Bodystyle/Series: **Sport Utility
Vehicle -**

Color: **White**

Mileage: **74,275
(Verified)**

Turn-in Mileage: **-**

VIN: **1FM5K8ABXLGC70360**

Work Order/
Stock Number: **46388321**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G626344X**

Vehicle Grade : **Grade 2.1**

Remarks: **-**

Announcements:

- Announcement:
- Prior police
- rear seats
- removed

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 255 / 60 R 18	Car Tire Size - LR 255 / 60 R 18	Car Tire Size - RR 255 / 60 R 18
Car Tire Size - RF 255 / 60 R 18	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - LR - Eagle Enforcer A/W	Tire Model - RR - Eagle Enforcer A/W	Tire Model - LF - Eagle Enforcer A/W
Tire Model - RF - Eagle Enforcer A/W		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Door	Chipped	-	10 Or More
	Right Front Door	Chipped	-	10 Or More
	Overall Vehicle	De-Identify	-	Removal Required
	Left Rear Wheel Cover	Curb Rash	-	1/2 To 1 Inch
	Left Front Wheel Cover	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Trunk/Cargo Mat	Missing	-	Replacement Required
	Left Rear Seat	Missing	-	Replacement Required
	Right Rear Seat	Missing	-	Replacement Required
	Left Front Fender	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Front Door	Chipped	-	2
	Rear Bumper Cover Upper	Chipped	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Multiple Dents/Paint Damage	-	2
	Rear Bumper Cover Upper	Misaligned	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.