



Approved CR

IAA Central NJ
426 Texas Road
Branch No 614
Morganville, NJ 07751
(732) 591-8173/(732) 591-8393
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019
HYUNDAI
SONATA**

Bodystyle/Series: **4 Door Sedan
ECO**

Color: **Silver**

Mileage: **26,107
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPE24AA0KH775838**

Work Order/
Stock Number: **46380204**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G100266W**

Vehicle Grade : **Grade 4.3**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 205 / 65 R 16	Car Tire Size - RF 205 / 65 R 16	Car Tire Size - LF 205 / 65 R 16
Car Tire Size - LR 205 / 65 R 16	LF Tires - 8/32 inch	LR Tires - 9/32 inch
RF Tires - 8/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - MASTERCRAFT
Tire Brand - Front Right - MASTERCRAFT	Tire Brand - Rear Left - MASTERCRAFT	Tire Brand - Rear Right - MASTERCRAFT
Tire Model - LF - Courser Quest	Tire Model - LR - Courser Quest	Tire Model - RF - Courser Quest
Tire Model - RR - Courser Quest		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
	Rear Bumper	Heavy Scratch	-	< 1/8 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.