Approved CR

America`s Auto Auction - Pensacola, Inc
6615 Mobile Highway
Pensacola, FL 32526-1264
850-972-8601/(850) 944-8482
Della.Smith@AmericasAutoAuction.com
WHOLESALE ASSESSMENT ONLY



| | |
|---|---|
| Make/Model: | **2018 FORD TRANSIT-350 CUTAWAY** |
| Bodystyle/Series: | **2 Door Vehicle T-350 DRW 138" WB 10360 GVWR V** |
| Color: | **WHITE** |
| Mileage: | **45,328 (Verified, 6 digits)** |
| Turn-in Mileage: | - |
| VIN: | **1FDRS6PMXJKB23061** |
| Work Order/ Stock Number: | **000356071** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | - |
| Vehicle Grade : | **Grade 2.7** |
| Remarks: | - |
| Announcements: | - |
| Certification : | **Not Certified** |
| Req. Prev. Repair Order: | - |

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **Yes** |
| Engine: | **6-Cylinder Gas** | Cruise Control: | **Yes** |
| Engine Size: | **3.7 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | **AM/FM CD** | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Vinyl Interior /GRAY** | Rear Defroster: | **No** |
| Airbag: | **Dual Air Bags** | Tilt Steering: | **Yes** |
| Seats: | - | Drive Type: | **Rear Wheel Drive** |
| Seat Count: | - | Brakes: | **Power Brakes** |

## Equipment


Additional Equipment:

| | | |
|---|---|---|
| ABS Brakes | Air Conditioning | Auxiliary Pwr Outlet |
| Bluetooth Connection | Brake Assist System | CD Player |
| Car Tire Size - LF tire size LT195/75SR16 | Car Tire Size - RR tire size LT195/75SR16 | Car Tire Size - RF tire size LT195/75SR16 |
| Car Tire Size - LR tire size LT195/75SR16 | Cruise Control | Cylinders - 6 |
| Daytime Running Lights | Driver Air Bag | Dual Rear Wheels |
| Empty Weight - 4290 lb | Independent Climate Control | Intermittent Wipers |
| Keyless Entry | LF Tires - 11/32 inch | LR Tires - 11/32 inch |
| Leather Steering Wheel | MP3 Radio | Master Key - 1key(s) |
| Motor Fuel Type - Gas | Pass. Air Bag | Power Brakes |
| Power Folding Mirrors | Power Lock | Power Mirrors |
| Power Steering | Power Windows | Privacy Glass |
| RF Tires - 11/32 inch | RR Tires - 11/32 inch | Rear View Mirror |
| Reverse Camera | Seat Trim - Vinyl | Side Airbags - Front |
| Steering Wheel Audio Control | Telematics | Tilt Steering Wheel |
| Tire Brand - Front Left - LF tire mfg Nexen | Tire Brand - Front Right - RF tire mfg Nexen | Tire Brand - Rear Left - LR tire mfg Nexen |
| Tire Brand - Rear Right - RR tire mfg Nexen | Transmission - Automatic Transmission w/ Overdrive | Trip Computer |
| Two-Wheel Drive | Wheels Front Left - Steel | Wheels Front Right - Steel |
| Wheels Rear Left - Steel | Wheels Rear Right - Steel | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Extra Photo 1 | Photo Only | Estimate Only | Unknown |
|  | Photo - Interior | Photo Only | Estimate Only | Unknown |
|  | Photo - Dash | Photo Only | Estimate Only | Unknown |
|   | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown |



## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Photo - Wheel | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 4 | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 3 | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 5 | Photo Only | Estimate Only | Unknown |
|  | Photo - Deck | Photo Only | Estimate Only | Unknown |
|  | Photo - Vin/Id Sticker | Photo Only | Estimate Only | Unknown |
|  | Stereo | Photo Only | Estimate Only | Unknown |
|  | Roof | Photo Only | Estimate Only | Unknown |
|  | Keys | Photo Only | Estimate Only | Unknown |
|  | Right Rear Tire | Photo Only | Estimate Only | Unknown |
|  | Photo - Rear | Photo Only | Estimate Only | Unknown |
|  | Left Rear Tire | Photo Only | Estimate Only | Unknown |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Door Panels | Photo Only | Estimate Only | Unknown |
|  | Left Front Tire | Photo Only | Estimate Only | Unknown |
|  | Right Front Tire | Photo Only | Estimate Only | Unknown |
|  | Extra Photo 2 | Photo Only | Estimate Only | Unknown |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Door | Oxidized | Report | > 12 Inches |
|  | Right Front Door | Chipped | Report | 5 |
|  | Deck Lid | Multiple Scratches Light | Report | 10 Or More |
|  | Front Bumper/Cover | Multiple Scratches Light | Report | 6 |
|  | Hood | Multiple Scratches Light | Report | 5 |
|  | Left Qtr Panel | Peeling | Report | 5 To 6 Inches |
|  | Left Front Door | Multiple Scratches Light | Report | 6 |
|  | Left Rear Door | Oxidized | Report | > 12 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Overall Vehicle | Repainted | Report | Non-Oem |
|  | Right Qtr Panel | Peeling | Report | 5 To 6 Inches |
|  | Rear Bumper/Cover | Rust | Report | > 12 Inches |
| [no photo] | Oil | Low Fluid | Report | Unacceptable |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.