Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**Silver**
Mileage:	**97,720 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC2LU219744**
Work Order/ Stock Number:	**46491118**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G131260X**
Vehicle Grade :	**Grade 3.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15	Car Tire Size - LR 195 / 65 R 15
Car Tire Size - RF 195 / 65 R 15	LF Tires - 8/32 inch	LR Tires - 4/32 inch
RF Tires - 8/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - BFGOODRICH
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - MICHELIN
Tire Model - RF - Advantage Control	Tire Model - RR - Defender T + H	Tire Model - LF - Advantage Control
Tire Model - LR - Defender T + H		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Front Wheel Cover	Curb Rash	-	> 12 Inches
	Right Rear Wheel Cover	Curb Rash	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Multiple Scratches Light	-	3
	Lf Door Handle Cap	Missing	-	Replacement Required
	Left Front Door Wind. Molding	Peeling	-	Replacement Required
	Left Rear Door Wind. Molding	Peeling	-	Replacement Required
	Spoiler	Peeling	-	> 12 Inches
	Right Qtr Panel	Multiple Scratches Light	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Drip Rail	Multiple Scratches Light	-	3
	Roof	Multiple Dents/Paint Damage	-	3
	Left Rear Seat Cushion	Stained	-	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.