Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2021 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**White**
Mileage:	**105,584 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC0MU246880**
Work Order/ Stock Number:	**46491116**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G133987Y**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /CREAM**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 16	Car Tire Size - LR 195 / 65 R 16	Car Tire Size - RR 195 / 65 R 16
Car Tire Size - RF 195 / 65 R 16	LF Tires - 6/32 inch	LR Tires - 9/32 inch
RF Tires - 6/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Assurance	Tire Model - RF - Assurance	Tire Model - LR - Assurance
Tire Model - LF - Assurance Maxlife		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Extra Photo 3	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat Cushion	Stained	-	Permanent
	Rear Bumper	Heavy Scratch	-	1 To 2 Inches
	Right Front Wheel Cover	Curb Rash	-	3 To 4 Inches
	Right Front Seat Cushion	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Seat Cushion	Stained	-	Permanent
	Front Bumper	Broken	-	Replacement Required
	Grille Molding	Heavy Scratch	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.