Approved CR

IAA Atlanta West
1871 Rome Hwy
Branch No 793
Rockmart, GA 30153
(470) 598-3740
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2020 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**Gray**
Mileage:	**77,734 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC7LU218718**
Work Order/ Stock Number:	**46491120**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G131261X**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Carriage**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15
Car Tire Size - LR 195 / 65 R 15	LF Tires - 6/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - STARFIRE
Tire Brand - Front Right - CROSSWIND	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - IRONMAN
Tire Model - RR - GR 906	Tire Model - RF - HP010 Plus	Tire Model - LR - Energy Saver A/s
Tire Model - LF - Solarus As		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Heavy Scratch	-	1/2 To 1 Inch
	Right Front Fender	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Wheel	Curb Rash	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/8 To 1/2 Inch
	Lift Gate	Heavy Scratch	-	1/8 To 1/2 Inch
	Left Front Fender	Heavy Scratch	-	1/8 To 1/2 Inch
	Left Front Seat Cushion	Stained	-	Permanent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.