



Approved CR

IAA Minneapolis/St. Paul
1280 Jackson Street
Branch No 526
St. Paul, MN 55117
(651) 488-0581/(651) 488-3644
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018
CHEVROLET
TAHOE**

Bodystyle/Series: **Sport Utility
Vehicle LS**

Color: **Gray**

Mileage: **62,541
(Verified)**

Turn-in Mileage: **-**

VIN: **1GNSKAEC5JR311505**

Work Order/
Stock Number: **45882714**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G621744V**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc


Equipment

Additional Equipment:

Car Tire Size - RF 255 / 65 R 18	Car Tire Size - RR 255 / 65 R 18	Car Tire Size - LR 255 / 65 R 18
Car Tire Size - LF 255 / 65 R 18	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 9/32 inch	RR Tires - 9/32 inch	Tire Brand - Front Left - FALKEN
Tire Brand - Front Right - FALKEN	Tire Brand - Rear Left - FALKEN	Tire Brand - Rear Right - FALKEN
Tire Model - RR - Wildpeak A/T4W	Tire Model - RF - Wildpeak A/T4W	Tire Model - LR - Wildpeak A/T4W
Tire Model - LF - Wildpeak A/T4W		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Warning - Tire Pressure	On	-	Unacceptable
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hitchplate Cover	Missing	-	Replacement Required
	Front Bumper	Bug Damage	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.