



Approved CR

IAA Oklahoma City
7300 N 1-35 Service RD
Branch No 421
Oklahoma City, OK 73121
(405) 475-0230/(405) 680-9204
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **Gray**

Mileage: **87,549
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC4LU220622**

Work Order/
Stock Number: **46344212**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G132705X**

Vehicle Grade : **Grade 3.4**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 55 R 15

Car Tire Size - RF 195 / 55 R 15

Car Tire Size - LF 195 / 55 R 15

Car Tire Size - LR 195 / 55 R 15

LF Tires - 2/32 inch

LR Tires - 6/32 inch

RF Tires - 2/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - MASTERCRAFT

Tire Brand - Front Right - MASTERCRAFT

Tire Brand - Rear Left - MASTERCRAFT

Tire Brand - Rear Right - MASTERCRAFT


Tire Model - RR - Stratus As

Tire Model - LF - Stratus As


Tire Model - LR - Stratus As

Tire Model - RF - Stratus As

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Tire	Worn	-	Replacement Required
	Front Bumper	Peeling	-	> 12 Inches
	Right Rear Door Molding	Peeling	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof Panel	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent
 Tire Information Driver Front Size: 195 / 15.8 / 15 Brand: MAXXIS/B47 Tread Depth: 20/32" Model: Stribos A4 Driver Rear Size: 195 / 15.8 / 15 Brand: MAXXIS/B47 Tread Depth: 6/32" Model: Stribos A4 Passenger Rear Size: 195 / 15.8 / 15 Brand: MAXXIS/B47 Tread Depth: 8/32" Model: Stribos A4 Passenger Front Size: 195 / 15.8 / 15 Brand: MAXXIS/B47 Tread Depth: 23/32" Model: Stribos A4	Left Front Tire	Worn	-	Replacement Required
	Windshield	Star In Glass	-	1 To 2 Inches
	Rf Mirror Cover	Peeling	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.