



Approved CR

America's Auto Auction - Richmond  
3600 Deepwater Terminal Road  
Richmond, VA 23234  
804-232-7355/804-232-1818  
richmond.fleet@americasaa.com  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD  
FUSION  
HIBRIDO**

Bodystyle/Series: **4 Door  
Vehicle SE  
4D SEDAN  
FWD**

Color: **GRAY**

Mileage: **63,736  
(Verified, 6  
digits)**

Turn-in Mileage: **-**

VIN: **3FA6P0LU2KR149474**

Work Order/  
Stock Number: **000844333**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G104190V**

Vehicle Grade : **Grade 4.3**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

#### Equipment

|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>Yes</b>               |
| Engine:                | <b>4-Cylinder Hybrid</b>      | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>2 L</b>                    | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>-</b>                      | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Dual Air Bags</b>          | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>Power</b>                  | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Power Brakes</b>      |

## Equipment

### Additional Equipment:

|                                          |                                                       |                                          |
|------------------------------------------|-------------------------------------------------------|------------------------------------------|
| 4th Passenger Door                       | ABS Brakes                                            | Adaptive Cruise Control                  |
| Air Conditioning                         | Automatic Headlights                                  | Auxiliary Pwr Outlet                     |
| Blind Spot Monitor                       | Bluetooth Connection                                  | Brake Assist System                      |
| Car Tire Size - RF tire size P225/50VR17 | Car Tire Size - LR tire size P225/50VR17              | Car Tire Size - LF tire size P225/50VR17 |
| Car Tire Size - RR tire size P225/50VR17 | Child Safety Locks                                    | Cruise Control                           |
| Cylinders - 4                            | Daytime Running Lights                                | Driver Air Bag                           |
| Dual Air Conditioning                    | Electrochromic Rearview Mirror                        | Empty Weight - 3695 lb                   |
| Engine Immobilizer                       | Floor Mats                                            | Front Wheel Drive                        |
| Front Wheel Drive                        | Independent Climate Control                           | Intermittent Wipers                      |
| Keyless Entry                            | Keyless Start                                         | LF Tires - 7/32 inch                     |
| LR Tires - 7/32 inch                     | Lane Departure System                                 | Master Key - 2key(s)                     |
| Motor Fuel Type - Other                  | Navigation System                                     | Pass-Through Rear Seat                   |
| Pass. Air Bag                            | Power Brakes                                          | Power Driver & Passenger Seat            |
| Power Driver Seat                        | Power Lock                                            | Power Mirrors                            |
| Power Steering                           | Power Trunk/Liftgate                                  | Power Windows                            |
| Privacy Glass                            | RF Tires - 7/32 inch                                  | RR Tires - 7/32 inch                     |
| Rain Sensor                              | Rear Defrost                                          | Rear Parking Aid                         |
| Remote Trunk Release                     | Reverse Camera                                        | Seat Trim - Cloth                        |
| Security System                          | Side Airbags - Front                                  | Steering Wheel Audio Control             |
| Telematics                               | Tilt Steering Wheel                                   | Tire Pressure Monitor System             |
| Traction Control                         | Transmission - Automatic Transmission w/<br>Overdrive | Trip Computer                            |
| Wheels Front Left - Aluminium            | Wheels Front Right - Aluminium                        | Wheels Rear Left - Aluminium             |
| Wheels Rear Right - Aluminium            |                                                       |                                          |

### Non Chargeable Damages

| Photo                                                                               | Item          | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|---------------|------------|---------------|----------|
|  | Extra Photo 3 | Photo Only | Estimate Only | Unknown  |
|  | Photo - Deck  | Photo Only | Estimate Only | Unknown  |

### Non Chargeable Damages

| Photo                                                                               | Item                       | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|----------------------------|------------|---------------|----------|
|    | Photo - Wheel              | Photo Only | Estimate Only | Unknown  |
|    | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown  |
|    | Overall Picture - Engine   | Photo Only | Estimate Only | Unknown  |
|    | Photo - Dash               | Photo Only | Estimate Only | Unknown  |
|    | Photo - Interior           | Photo Only | Estimate Only | Unknown  |
|    | Extra Photo 1              | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 2              | Photo Only | Estimate Only | Unknown  |
|  | Photo - Rear               | Photo Only | Estimate Only | Unknown  |
|  | Door Panels                | Photo Only | Estimate Only | Unknown  |
|  | Keys                       | Photo Only | Estimate Only | Unknown  |
|  | Roof                       | Photo Only | Estimate Only | Unknown  |
|  | Left Rear Seat             | Photo Only | Estimate Only | Unknown  |
|  | Stereo                     | Photo Only | Estimate Only | Unknown  |

| Non Chargeable Damages                                                            |                        |            |               |          |
|-----------------------------------------------------------------------------------|------------------------|------------|---------------|----------|
| Photo                                                                             | Item                   | Damage     | Action        | Severity |
|  | Steering Wheel         | Photo Only | Estimate Only | Unknown  |
|  | Photo - Vin/Id Sticker | Photo Only | Estimate Only | Unknown  |

| Chargeable Damages                                                                |                   |                                |        |               |
|-----------------------------------------------------------------------------------|-------------------|--------------------------------|--------|---------------|
| Photo                                                                             | Item              | Damage                         | Action | Severity      |
|  | Right Front Wheel | Heavy Scratch                  | Repair | 5 To 6 Inches |
|  | Left Front Wheel  | Heavy Scratch                  | Repair | 1 To 2 Inches |
|  | Hood              | Multiple Dents/No Paint Damage | PDR    | 2             |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.