Approved CR

Greater Rockford Auto Auction
5937 Sandy Hollow Road
Rockford, IL 61109
(815) 874-7800/(815) 874-7009
BSchneider@graa.net
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 1500**
Bodystyle/Series:	**Quad Cab TRADESMAN QUAD CAB 2WD SWB**
Color:	**WHITE**
Mileage:	**85,365 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1C6RR6FT8JS330340**
Work Order/ Stock Number:	**000667097**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G421845V**
Vehicle Grade :	**Grade 2.9**
AutoGrade :	**2.9 - Below Average**
Remarks:	-
Announcements:	• HEMI
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GY**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

ABS Brakes	Air Conditioning	Automatic Headlights
Bedliner	Bluetooth Connection	Brake Assist System
Car Tire Size - RF tire size LT265/70SR17	Car Tire Size - RR tire size LT265/70SR17	Car Tire Size - LR tire size LT265/70SR17
Car Tire Size - LF tire size LT265/70SR17	Child Safety Locks	Cruise Control
Cylinders - 8	Daytime Running Lights	Driver Air Bag
Electrochromic Rearview Mirror	Engine Immobilizer	Floor Mats
Heated Mirrors	Intermittent Wipers	Keyless Entry
LF Tires - 10/32 inch	LR Tires - 9/32 inch	MP3 Radio
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	Privacy Glass
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Rear View Mirror
Running Board	Seat Trim - Cloth	Side Airbags - Front
Spare Tire	Stereo - AM/FM Radio	Tilt Steering Wheel
Tire Brand - Front Left - LF tire mfg Goodyear	Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear
Tire Brand - Rear Right - RR tire mfg Goodyear	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Turn Signal Mirrors	Two-Wheel Drive
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel	XM Radio	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Multiple Scratches Heavy	Repair	3
	Hood	Dent(S) W/No Paint Dmg	PDR	1 To 2 Inches
	Left Bed Side	Chipped	Touch Up	7
	Left Rocker Panel	Peeling	Repair	6 To 7 Inches
	Left Front Fender	Rust	Repair	2 To 3 Inches
	Left Front Seat	Torn	Repair	6 To 7 Inches
	Right Bed Side	Multiple Dents/No Paint Damage	Repair	2
	R Cab Corner Panel	Dent(S) W/No Paint Dmg	Repair	1 To 2 Inches
	Rear Metal Bumper Painted	Rust	Repair	> 12 Inches
	Roof	Dent(S) W/No Paint Dmg	Repair	4 To 5 Inches
	Tailgate	Dent(S) W/ Paint Dmg	Repair	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.