Approved CR

Greater Rockford Auto Auction
5937 Sandy Hollow Road
Rockford, IL 61109
(815) 874-7800/(815) 874-7009
BSchneider@graa.net
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2019 FORD SUPER DUTY F-250 SRW**
Bodystyle/Series:	**Crew Cab XL CREW CAB 4WD SWB**
Color:	**SILVER**
Mileage:	**97,169 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**1FT7W2B60KEF35197**
Work Order/ Stock Number:	**000667098**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G631753W**
Vehicle Grade :	**Grade 4.4**
AutoGrade :	**4.4 - Clean**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GY**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Air Conditioning	Automatic Headlights	Bluetooth Connection
Brake Assist System	Car Tire Size - RR tire size LT245/75SR17	Car Tire Size - RF tire size LT245/75SR17
Car Tire Size - LR tire size LT245/75SR17	Car Tire Size - LF tire size LT245/75SR17	Child Safety Locks
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	Empty Weight - 6446 lb	Engine Immobilizer
Heated Mirrors	Intermittent Wipers	LF Tires - 9/32 inch
LR Tires - 8/32 inch	Master Key - 1key(s)	Motor Fuel Type - Other
Owner's Manual	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	RF Tires - 9/32 inch
RR Tires - 7/32 inch	Reverse Camera	Seat Trim - Cloth
Security System	Side Airbags - Front	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Firestone
Tire Brand - Front Right - RF tire mfg Firestone	Tire Brand - Rear Left - LR tire mfg Firestone	Tire Brand - Rear Right - RR tire mfg Firestone
Tire Pressure Monitor System	Tow Hitch	Traction Control
Transmission - Automatic Transmission	Trip Computer	Turn Signal Mirrors
Wheels Front Left - Steel	Wheels Front Right - Steel	Wheels Rear Left - Steel
Wheels Rear Right - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown



Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Chipped	Touch Up	4
	Left Bed Side	Multiple Scratches Light	Touch Up	3
	Left Rocker Panel	Heavy Scratch	Repair	2 To 3 Inches
	L Cab Corner Panel	Chipped	Touch Up	2
	Left Front Fender	Chipped	Touch Up	2
	Right Bed Side	Dent(S) W/ Paint Dmg	Repair	5 To 6 Inches
	Tonneau Cover	Chipped	Touch Up	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.