Approved CR

Carriage Trade Auto Auction
1200 Ridge Pike
Conshohocken, PA 19428
215-CAR-SALE/(610) 834-8274
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 DODGE DURANGO**
Bodystyle/Series:	**Sport Utility Vehicle PURSUIT**
Color:	**BLACK**
Mileage:	**105,758 (Digital)**
Turn-in Mileage:	-
VIN:	**1C4RDJFG4LC352376**
Work Order/ Stock Number:	**0181117**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G620890Y**
Vehicle Grade :	**Grade 2.6**
Remarks:	-
Announcements:	• Previous police vehicle • PRIOR POLICE - OVER 100K MILES
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: YES

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**- /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**All Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

Automatic Headlights	Auxiliary Audio Input	Backup camera and monitor
Bluetooth Connection	Brake Assist System	Car LF Tires - 6/32 inch
Car LR Tires - 6/32 inch	Car RF Tires - 6/32 inch	Car RR Tires - 6/32 inch
Car Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE	Child Safety Locks	Cross - Traffic Alert
Cylinders - 6	Driver Adjustable Lumbar	Driver Vanity Mirror
Electrochromic Rearview Mirror	Electronic Stability Control	Engine Immobilizer
Floor Mats	Fog Lamps	Front Head Air Bag
Heated Mirrors	Ignition Key - 2key(s)	Independent Climate Control
Intermittent Wipers	Keyless Entry - Left	Keyless Start
Knee Air Bag	LF Tires - 6/32 inch	LR Tires - 6/32 inch
Leather Steering Wheel	MP3 Radio	Misc. Special Features - Rear Collision Mitigation
Pass-Through Rear Seat	Pass. Air Bag	Passenger Air Bag Sensor
Passenger Vanity Mirror	Power Driver Seat	Power Mirrors
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 6/32 inch
Rear AC	Rear Bench Seat	Rear Head Air Bag
Rear Parking Aid	Rear Spoiler	Side Airbags - Front
Smart Device Integration	Spare Tire - Full Size	Spare Tire Tread - 8/32 inch
Spare Wheel - Steel	Steering Wheel Audio Control	Telematics
Tilt Steering Wheel	Tire LF - 6/32 inch	Tire Pressure Monitor System
Tire RF - 6/32 inch	Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE	Tire Size - LF: P265/60TR18 LR: P265/60TR18 RF: P265/60TR18 RR: P265/60TR18 SP: FULL SIZE
Tow Hitch	Transmission - Automatic Transmission	Trip Computer
Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	Wheels Rear Left - Aluminium
Wheels Rear Right - Aluminium		

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Extra Photo 9	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-

Chargeable Damages

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Front Bumper	Scuffed	Estimate Only	5 To 6 Inches
[no photo]	Hood	Multiple Scratches Light	Estimate Only	5
[no photo]	Left Front Door	Multiple Scratches Light	Estimate Only	4
[no photo]	Left Front Fender	Multiple Scratches Light	Estimate Only	5
	Left A Pillar	Multiple Holes	Estimate Only	3
[no photo]	Left Front Mirror Housing	Hole(S)	Estimate Only	2 To 3 Inches
[no photo]	Left Rear Door	Multiple Scratches Light	Estimate Only	4
[no photo]	Left Qtr Panel	Multiple Scratches Light	Estimate Only	5
[no photo]	Trunk Trim	Hole(S)	Estimate Only	3 To 4 Inches
[no photo]	Right Rear Door	Multiple Scratches Light	Estimate Only	3
[no photo]	Right Qtr Panel	Multiple Scratches Light	Estimate Only	4
[no photo]	Right Front Fender	Multiple Scratches Light	Estimate Only	4
[no photo]	Right Front Mirror Housing	Hole(S)	Estimate Only	2 To 3 Inches
	Roof	Hole(S)	Estimate Only	2 To 3 Inches
	Headlining	Hole(S)	Estimate Only	2 To 3 Inches
	Left Front Seat	Torn	Estimate Only	3 To 4 Inches
[no photo]	Left Rear Door Panel	Missing	Estimate Only	Replacement Required
[no photo]	Right Rear Door Panel	Missing	Estimate Only	Replacement Required
[no photo]	Right Rear Seat	Missing	Estimate Only	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.