Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD TRANSIT CONNECT**
Bodystyle/Series:	**4 Door Vehicle XLT PASSENGER WAGON WAGON**
Color:	**SILVER**
Mileage:	**71,743 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**NM0GE9F29L1436466**
Work Order/ Stock Number:	**000116236**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 2.8**
AutoGrade :	**2.8 - Below Average**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**Front Wheel Drive**

Equipment

Seat Count: -

Brakes: **Power Brakes**

Additional Equipment:

3rd Row Seat	4th Passenger Door	ABS Brakes
Air Conditioning	Automatic Headlights	Auxiliary Pwr Outlet
Blind Spot Monitor	Bluetooth Connection	Brake Assist System
Car Tire Size - LF tire size P215/55HR16	Car Tire Size - LR tire size P215/55HR16	Car Tire Size - RF tire size P215/55HR16
Car Tire Size - RR tire size P215/55HR16	Child Safety Locks	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Dual Air Conditioning	Empty Weight - 4028 lb	Engine Immobilizer
Floor Mats	Fog Lamps	Front Wheel Drive
Front Wheel Drive	Heated Mirrors	Independent Climate Control
Intermittent Wipers	Keyless Entry	LF Tires - 6/32 inch
LR Tires - 5/32 inch	Lane Departure System	Leather Steering Wheel
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass. Air Bag
Power Brakes	Power Driver Seat	Power Folding Mirrors
Power Lock	Power Mirrors	Power Steering
Power Windows	Privacy Glass	RF Tires - 6/32 inch
RR Tires - 6/32 inch	Rain Sensor	Rear AC
Rear Defrost	Rear Parking Aid	Reverse Camera
Seat Trim - Cloth	Side Airbags - Front	Steering Wheel Audio Control
Telematics	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Goodyear
Tire Brand - Front Right - RF tire mfg Goodyear	Tire Brand - Rear Left - LR tire mfg Goodyear	Tire Brand - Rear Right - RR tire mfg Goodyear
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission w/ Overdrive
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel	Wheels Rear Right - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	3rd Row Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Multiple Dents/No Paint Damage	PDR	Pdr-4 Dents
	Left Front Wheel Cover	Missing	Replace	Replacement Required
	Left Rear Door	Multiple Dents/No Paint Damage	PDR	8
	Left Rear Wheel Cover	Peeling	Refinish	> 12 Inches
	Rear Bumper/Cover	Multiple Scratches Heavy	Touch Up	7
	Roof	Multiple Dents/No Paint Damage	PDR	10 Or More
	Right Front Wheel Cover	Broken	Replace	Replacement Required
	Hood	Hail Damage	PDR	10 Or More
	Left Qtr Panel	Multiple Dents/No Paint Damage	PDR	8
	Left Front Door	Multiple Dents/No Paint Damage	PDR	Pdr-6 Dents

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.