Approved CR

Mid Kansas Auto Auction Wichita
4716 S. Santa Fe
Wichita , KS 67216
316-500-7700/316-500-7701
codyd@mksaa.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 HYUNDAI ELANTRA**
Bodystyle/Series:	**4 Door Sedan SE 4D SEDAN AT**
Color:	**SILVER**
Mileage:	**74,860 (Verified, 6 digits)**
Turn-in Mileage:	-
VIN:	**5NPD74LF9LH613438**
Work Order/ Stock Number:	**000116122**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 3.4**
AutoGrade :	**3.4 - Average**
Remarks:	-
Announcements:	-
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	-	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Power Brakes**

Equipment


Additional Equipment:

ABS Brakes	Air Conditioning	Bluetooth Connection
Brake Assist System	Car Tire Size - RF tire size P195/65TR15	Car Tire Size - LR tire size P195/65TR15
Car Tire Size - LF tire size P195/65TR15	Car Tire Size - RR tire size P195/65TR15	Child Safety Locks
Collision Avoidance	Cruise Control	Cylinders - 4
Daytime Running Lights	Driver Air Bag	Dual Air Conditioning
Empty Weight - 2844 lb	Floor Mats	Front Wheel Drive
Front Wheel Drive	Independent Climate Control	Intermittent Wipers
Keyless Entry	LF Tires - 6/32 inch	LR Tires - 6/32 inch
Lane Departure System	MP3 Radio	Master Key - 1key(s)
Motor Fuel Type - Gas	Pass-Through Rear Seat	Pass. Air Bag
Power Brakes	Power Lock	Power Mirrors
Power Steering	Power Windows	RF Tires - 5/32 inch
RR Tires - 4/32 inch	Rear Defrost	Remote Trunk Release
Reverse Camera	Seat Trim - Cloth	Security System
Side Airbags - Front	Spare Tire	Steering Wheel Audio Control
Stereo - AM/FM Radio	Tilt Steering Wheel	Tire Brand - Front Left - LF tire mfg Bridgestone
Tire Brand - Front Right - RF tire mfg Bridgestone	Tire Brand - Rear Left - LR tire mfg Bridgestone	Tire Brand - Rear Right - RR tire mfg Bridgestone
Tire Pressure Monitor System	Traction Control	Transmission - Automatic Transmission
Trip Computer	Wheels Front Left - Steel	Wheels Front Right - Steel
Wheels Rear Left - Steel		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Dent(S) W/ Paint Dmg	Refinish	1/2 To 1 Inch
	Right Qtr Panel	Multiple Dents/No Paint Damage	PDR	8
	Rear Bumper/Cover	Cracked	Replace	5 To 6 Inches
	Rear Bumper/Cover	Multiple Scratches Heavy	Touch Up	6
	Front Right Bumper/Cover	Multiple Scratches Heavy	Touch Up	2
	Right Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Right Rear Door	Multiple Dents/No Paint Damage	PDR	Pdr-3 Dents
	Front Bumper Cover Lower	Broken	Replace	Replacement Required
	Hood	Chipped	Touch Up	3
	Front Left Bumper/Cover	Multiple Scratches Heavy	Touch Up	2
	Left Front Door	Chipped	Touch Up	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Dent(S) W/ Paint Dmg	Repair	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.