Approved CR

IAA Bowling Green
710 Woodford Ave
Branch No 658
Bowling Green, KY 42101
(270) 843-3555/(270) 843-4897
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**Silver**
Mileage:	**28,371 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC3JU077076**
Work Order/ Stock Number:	**46484513**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G132645V**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15
Car Tire Size - LR 195 / 65 R 15	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Kinergy GT H436	Tire Model - LR - Kinergy GT H436	Tire Model - RF - Kinergy GT H436
Tire Model - RR - Kinergy GT H436		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof Panel	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY,

WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.